Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Date: June 2025

WATER

LAKESHORE

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of June 27 **Equipment Issues:**

- Tachmina flow sensor failure at Huronville South (replaced)
- Tachmina flow sensor failure at Murdoch Glen (replaced)
- Point Clark HLP 2 expenditure request issued for removal and inspection
- Blair's Grove reservoir drained, re-chlorinated, cycled and put into service
- Huronville South HLP1 ground fault error. Found loose connection on the motor. Repairs made and HLP1 was put back in service
- Chlorine board leak repaired at Blair's Grove
- Point Clark WP and HLP failures. SCADA setpoints changed after a brief power outage caused by an electrical storm. Issue has been resolved
- Chlorine pump failure at Point Clark. Motor burnt out and replaced with an entirely new pump

Planned Maintenance:

- Annual third-party analyzer, flow meter and level transmitter calibrations completed
- Sodium Silicate tank emptied and cleaned at Blair's Grove. Replaced suction and feed lines as the chemical thickened over time due to lack of use
- RW Singer valve rebuilt in Blair's Grove

Main breaks and Leaks:

- Two service leaks at 420 Albert st
- Service leak at 252 Huron st
- Service leak at 601 Tuscarora rd

Power Outages: Brief outages in Point Clark and Murdoch Glen due to an electrical storm (less than a minute)

Complaints / Requests:

- 106 Lurgan Lane discoloured water (increased silicate dosage at Blair's Grove and lines flushed)
- 207 Brown st low pressure (pressure tested and was 70psi)

Locates: (see Township master list)

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

LUCKNOW

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of June 27

Non-Compliances: None Equipment Issues: None Planned Maintenance:

 Annual third-party analyzer, flow meter and level transmitter calibrations completed

Main breaks and Leaks: None

Power Outages: None Complaints / Requests:

- 752 Stauffer discoloured water. Increased auto-flusher run time from 5 mins a day to 20 mins every Monday, Wednesday and Friday. Scheduled to sample for metals in July.
- South Delhi st discoloured water. Flushed at blowoffs

Locates: (see Township master list)

RIPLEY

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of June 27

Non-Compliances: None Equipment Issues: None Planned Maintenance:

- Annual third-party analyzer, flow meter and level transmitter calibrations completed
- Diaphragm kit replaced on Well 3 chlorine pump

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

WHITECHURCH

Adverse Samples: None

Microbiological Sampling Summary: No adverse bacteriological sample results as of June 27

Non-Compliances: None

Equipment Issues:

 Well pump 1 uncommanded start/stop alarms. Extended alarm delay so that pump would continue to run

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

Planned Maintenance:

- Annual third-party analyzer, flow meter and level transmitter calibrations completed
- Annual generator service completed
- Generator fuel tank replaced

Main breaks and Leaks: None

Power Outages: None

Complaints / Requests: None

Locates: (see Township master list)

WASTEWATER

LUCKNOW

Exceedances: None

Non-Compliances: None

Equipment Issues:

- Electrician looking into parts to get pump #2 installed and working at lagoon. Waiting on quote
- Main breaker failure at Lucknow SPS. Expenditure request issued for replacement breaker

Planned Maintenance:

- Annual third-party flow meter and level transmitter calibrations completed
- Lucknow SPS cleaned by third party
- Annual generator service completed at Lucknow SPS

Sewer Main Breaks and Leaks: None

Power Outages: Power outage at the Lucknow SPS due to a main breaker

failure.

Total Locates: (see Township master list)

RIPLEY

Exceedances: None
Non-Compliances: None

Equipment Issues: 15 HP replacement pump now in stock

Planned Maintenance:

 Annual third-party flow meter and level transmitter calibrations completed

Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

• Ripley SPS cleaned by third party

Ripley Arena SPS cleaned by third party

Lagoon inlet chamber cleaned by third party

Sewer Main Breaks and Leaks: None

Power Outages: None **Complaints:** None

Total Locates: (see Township master list)

Ongoing Issues/Recommendations

WATER:

Lakeshore

- Replace both HLP Singer valves with swing check valves in Point Clark
- Flow paced chlorine dosing in Point Clark. Working on quote to replace chlorine board and feed pumps. Pumps will dose a common header, reducing the necessary chlorine pumps from 4 to 2 (lower maintenance cost) and result in a more consistent residual.
- Control valves 2 and 3 and an ARV in Murdoch Glen need serviced. Waiting on quote
- Rebuild chlorine boards at all 4 sites, starting at Point Clark. Working on quotes

Ripley

- HLP piping replacement in the Ripley wellhouse. Working on quotes
- Replace Endress & Hauser analyzer at Elevated Tank

Lucknow

- Piping replacement in Lucknow well 5
- Replace Endress & Hauser analyzer at well 5

Whitechurch

Replace Endress & Hauser analyzer

WASTEWATER:

Lucknow:

- Waiting for electrician to source parts for pump install at lagoon. Ongoing.
- SPS louvres not operating automatically. Arranging quotes for repair

Ripley:

Lagoon blower has oil leak. Plan to repair ASAP

OTHER:

ACW: Thomas McCarthy contacted about sample station in South Lucknow