

# Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

---

**Date:** February 2026

## **WATER**

### **LAKESHORE**

**Adverse Samples:** None

**Microbiological Sampling Summary:** No adverse bacteriological sample results as of February 20<sup>th</sup>

**Non-Compliances/AWQI:** None

**Equipment Issues:**

- Leaking chlorine board repaired in Point Clark (January 25<sup>th</sup>)
- Frozen well piping thawed at Blairs Grove (January 27<sup>th</sup>)
- Communications fault on Sensaphone alarm autodialer corrected at Point Clark
- Leaking chlorine board repaired in Huronville South
- HLP5 uncommanded start/failed to stop alarms corrected at Murdoch Glen. Found loose control wiring in HLP5 MCC. Re-terminated loose wiring and replaced PLC drive cabinet and run relays.
- Repaired faulty Tachmina at Point Clark

**Planned Maintenance:**

- Restricted access plate re-installed on Point Clark Standpipe ladder
- Generator fuel tank inspections completed at Point Clark and Murdoch Glen
- Hydrant 219 on Boardwalk/Heritage repaired and returned to service

**Main breaks and Leaks:**

- Emergency shut off for 300 Highland Dr for a leak on the private side of the service
- Emergency shut off at 404 Ash st for a leak in their crawlspace

**Power Outages:** None

**Complaints / Requests:**

- 306 Lewis Rd – hard water
- 956 Bogdanovic Way – hard water
- 3 Lowry Lane – rusty water

**Locates:** (see Township master list)

### **LUCKNOW**

**Adverse Samples:** None

**Microbiological Sampling Summary:** No adverse bacteriological sample results as of February 20<sup>th</sup>

# Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

---

**Non-Compliances/AWQI:** None

**Equipment Issues:**

- Repaired leaking chlorine board at well 4

**Planned Maintenance:**

- Analyzer and sample tap drain line replaced in Well 5
- Generator fuel tank inspection completed on portable unit
- Hydrant 144 on Campbell/Montgomery repaired and returned to service

**Main breaks and Leaks:** None

**Power Outages:** None

**Complaints / Requests:** None

**Locates:** (see Township master list)

## RIPLEY

**Adverse Samples:** None

**Microbiological Sampling Summary:** No adverse bacteriological sample results as of February 20<sup>th</sup>

**Non-Compliances/AWQI:** None

**Equipment Issues:** None

**Planned Maintenance:**

- Generator fuel tank inspections completed at the wellhouse and tower. Tower generator needs a tank filling whistle installed – scheduled for February 26<sup>th</sup>

**Main breaks and Leaks:**

- Watermain repair completed on Park st, near McGill

**Power Outages:** None

**Complaints / Requests:** None

**Locates:** (see Township master list)

## WHITECHURCH

**Adverse Samples:** None

**Microbiological Sampling Summary:** No adverse bacteriological sample results as of February 20<sup>th</sup>

**Non-Compliances/AWQI:** None

**Equipment Issues:** None

**Planned Maintenance:**

- Generator fuel tank inspection completed

**Main breaks and Leaks:** None

**Power Outages:** None

**Complaints / Requests:** None

**Locates:** (see Township master list)

# Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

---

## WASTEWATER

### LUCKNOW

**Exceedances:** None

**Non-Compliances:** None

**Equipment Issues:**

- Replaced broken electric heater in the SPS basement

**Planned Maintenance:**

- Continued diverting aerated lagoon flow to the storage lagoon. Received approval from MECP Inspector and met with BM Ross on October 31<sup>st</sup> to discuss possible solutions for poor drainage. Test holes dug on November 20<sup>th</sup>. Waiting on report from BM Ross for next steps
- Generator fuel tank inspection completed at SPS

**Sewer Main Breaks and Leaks:**

- Flushed sanitary main upstream and downstream of 811 Havelock to clear up an ice blockage.

**Power Outages:** None

**Total Locates:** (see Township master list)

### RIPLEY

**Exceedances:** None

**Non-Compliances:** None

**Equipment Issues:**

- Blown fuses replaced on Lagoon hydro transformer

**Planned Maintenance:**

- Generator fuel tank inspection completed at SPS

**Sewer Main Breaks and Leaks:** None

**Power Outages:**

- Extended outage at the Lagoon due to transformer issue

**Complaints:** None

**Total Locates:** (see Township master list)

# Ontario Clean Water Agency Summary for the Township of Huron-Kinloss

---

## Ongoing Issues/Recommendations

### WATER:

#### Lakeshore

- Replace both HLP Singer valves with swing check valves in Point Clark

#### Ripley

- HLP piping replacement in the Ripley wellhouse.
- Replace Endress & Hauser analyzer at Elevated Tank

#### Lucknow

- Piping replacement in Lucknow well 4
- Replace Endress & Hauser analyzer at well 5

#### Whitechurch

- Replace Endress & Hauser analyzer

### WASTEWATER:

#### Lucknow:

- Upgrade chemical feed pumps.

#### Ripley:

- Upgrade chemical feed pumps.