

**Ontario Clean Water Agency (OCWA)**  
**January report**  
**2025**

Since we are taken over operations of water and wastewater for Huron Kinloss Dec. 31, 2024 @1200

-4 Water turn off for repairs/all on homeowners' side  
-9 locates

**Callouts**

Jan 1 – Ripley well high level- water coming back from distribution system, will isolate each High lift and to find issue.

Jan 2 – Point Clark High lift failed to start

Jan 26 and 27 Power outages Scada down

**Lucknow Lagoon spill**

We had a overflow at Lucknow lagoon at valve box chamber on Jan 16. Spill was reported to MECP. Issue was fixed so it can not happen again.

**Complaints**

Low pressure issue on Lake Range Drive. Hydrants were pressure tested to find problem area.

Flushed system to get air out. Seems to be back to normal. Will continue to monitor.

Water quality issue, spoke with homeowner, problem was with the home

**Operational**

Sample stations were all frozen, OCWA thawed out 9 stations and shut them off at curb stop.

Hydrants markers were installed for Inverlyn Lake Estates

Hydrant Markers Install in Lucknow

2 heaters not working at Ripley SPS (waiting on quotes)

Heater failed at Well house 4 in Lucknow (waiting on quotes)

Heater needs replaced at well house 5 is bad shape. (waiting on quotes)