

**Municipality of Huron-Kinloss
Pine River Water Quality Monitoring Program
2023 Sampling Results**

GREEN	Below Guideline
RED	=> 100 cfu/100mL
GREY	No Data

**E. Coli (cfu/100mL)
Sample Date**

SAMPLE ID	LOCATION	Mar 27	April 24	May 23	Jun 19	Jul 17	Aug 15	Sep 11	Oct 10	Nov 6
PR1	Pine River-Bridge on Lake Range Road, south of Lurgan Road	90	46	40	20	68	26	49	1420	76
PR3	South Pine River-Bridge on Hwy. 21 at 6th Conc.	84	32	130	56	100	20	36	1800	112
PR4	Pine River Tributary-Bridge on Hwy. 21 North of 6th Conc.	72	31	120	170	22	48	14	1440	62
PR5	Pine River Tributary-Bridge on Hwy. 21 North of 8th Conc.	142	128	68	30	86	76	40	1580	56
PR6	South Pine River-Bridge on Sideroad 25 North of 6th Conc.	78	40	28	60	64	108	720	3700	53
PR7 - Upstream	Clark Creek-Culvert on Sideroad 25 South of 4th Conc.	114	< 2	6	144	56	48	220	760	16
PR8	South Pine River-Culvert on the 15th North of 6th Conc.	40	58	144	172	228	108	62	1560	118
PR9	Pine River-Bridge on the 15th South of 10th Conc.	94	66	34	6	160	54	90	2380	64
PR10	Royal Oak Creek-Bridge on the 15th North of the 12th Conc.	50	156	22	66	134	78	34	6000	42
PR11	Royal Oak Creek-Culvert on Sideroad 5 north Huron-Kincardine East	284	286	30	70	148	124	126	2620	23
PR12	Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 12th Conc.	6	12	68	322	1800	80	120	920	50
PR13	South Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 8th Conc.	200	46	116	370	760	720	46	1760	74
PR17 - Upstream	Pine River Tributary-Southern Culvert on South Baseline Road North of 4th Conc.	200	98	164	170	72	82	150	1440	40
PR18 - Upstream	Pine River Tributary- Middle Culvert on South Baseline Road North of 4th Conc.	16	26	70	76	176	64	880	900	22
PR19 - Upstream	Clark Creek-Southern Culvert on South Baseline Road North of 2nd Conc.	24	14	26	40	92	66	10	600	22
PR20	Beach at Hwy. 86 -Amberely Road.	2	2	< 2	2	200	22	6	20	2
PR21	Beach off of Attawandron Road-Public Walkway	4	< 2	4	8	122	2	30	34	52
PR22	Beach-Point Clark Swimming Area	2	4	< 2	< 2	180	8	18	12	58
PR23	Lurgan Beach-Public Walkway	220	10	2	< 2	100	8	18	Overgrown	30
PR24	Beach at 6th Conc.	38	4	< 2	2	320	4	8	Overgrown	26
PR25	Beach at 8th Conc.	2	4	< 2	< 2	70	10	< 2	Overgrown	8
PR26	Beach at 10th Conc.	4	8	< 2	< 2	34	30	2	Overgrown	2
PR27	Boyd Creek at Hwy. 21 before Amberely	34	38	34	26	158	26	24	900	58
PR29	Boyd Creek on Sideroad 20 North of 6th Conc.	102	74	104	296	132	70	58	1400	36
PR30	Eighteen Mile Creek at Hwy. 21 before Amberely	380	50	80	20	92	40	48	2300	48
PR32	Eighteen Mile Creek on the 15th North of 2nd Conc.	76	30	82	54	42	98	10	5300	60
B4	Clark Creek at the Lake	28	20	46	30	134	20	32	780	36
5	Ditch at field drain outlet, Lake Range Road	16	10	22	96	106	106	20	640	238
6	New outlet to Clark Creek across from 3491 2nd Conc.	24	28	32	82	114	30	76	680	50
8	Jardine Creek at Abenaki St.	8	66	254	296	64	108	68	196	148
9	Jardine Creek at Seneca	30	4	Dry	Dry	< 2	94	Dry	118	14
12	Halfway to lake from Road	70	18	30	152	134	50	Dry	164	2
13	CSP where creek crosses Huron Rd.	14	6	146	84	90	500	1400	84	< 2
17	Outlet in Jardine Creek between sites 11 & 12	58	8	38	125	75	28	88	880	158