Date: May, 2024

Prepared by: Sarah Telford/Ryan MacKay/Jeff Johnston

# There were 89 locates completed and 16 project locates for April

### WATER

# **Lakeshore**

Adverse Samples: No adverse bacteriological sample results

Non-Compliances: None.

**Equipment Issues:** 

• Blairs Grove(BG):

New chlorine Analyzer was installed

- Huronville(HV):
  - Generator Testing completed
  - o Both high lift pumps are on and ready in preparation of Kincardine needing water
- Murdoch Glen(MG):
  - Pump Integration has been completed
  - o Fuel tank upgrade work completed
- Point Clark (PC):
  - Currently waiting on quotes for Portable generator procedures, hoping to make them interchangeable for all the sites
  - o Portable generator being stored here

### **General Information:**

Working on all required Work Orders and all samples were taken

- Meter in Elliot Construction pit replacement is scheduled
- Flushing is completed
- Valve turning all flushing in HK is completed
- Kemptons will be vacuuming out air relief chambers and we will monitor how long it takes them to fill up and whether it is ground or chlorinated water

### Alarms:

- HV No flow alarm due to a plugged tacmina
- MG Zone 3 low pressure , false read

#### Main Breaks and Leaks:

- There was one service leak on Cherrywood Cres

### **Power Outages:**

- 27th - power outage

### Inquiries and Complaints:

None to Report

Locates: (see Township master list)



Date: May, 2024

Prepared by: Sarah Telford/Ryan MacKay/Jeff Johnston

### Lucknow

Valve turning will be complete by month end

### **Adverse Samples:**

- None

#### **Non-Compliances:**

None

#### **Equipment Issues:**

- L4
  - С
- L5

### **Water Tower:**

Nothing to report

#### **General Information:**

Working on routine monthly maintenance

- MECP Inspection is underway
- Manhole repairs to be scheduled with SGS
- Operators are diligently working to clean out the firehall
- L5 Roof was repaired

# Alarms:

- L5 - low chlorine (hole in the tubing)

### Main breaks and Leaks:

- None to Report

#### **Power Outages:**

None to Report

### **Inquiries and Complaints:**

None to Report

Locates: (see Township master list)

## **Ripley**

Working on routine monthly maintenance

Adverse Samples: None.

Non-Compliances: None.

Equipment Issues: None.

Alarms:



Date: May, 2024

Prepared by: Sarah Telford/Ryan MacKay/Jeff Johnston

Ripley Well:

- The well is offline due to the VFD failure (current use was for sampling only)

• Elevated Tower:

----

#### **General Information:**

Working on all required Work Orders and samples were taken

- The roof has been repaired

- Manhole repairs to be scheduled with SGS

- Flushing has started, duplicate hydrants on the GIS mapping system need to be removed

Alarms: None to Report

Main breaks and Leaks: None

**Power Outages:** 

- 27th Power outage

**Inquiries and Complaints:** None reported.

**Locates:** (see Township master list)

## **Whitechurch**

Adverse Samples: No adverse bacteriological sample results

Non-Compliances: None.

**Equipment Issues:** None to report.

**General Information:** 

All required samples were taken

Routine monthly maintenance completed

- Fuel tank has been inspected, waiting for report

#### Alarms:

None to Report

Main breaks and Leaks: None reported.

**Power Outages:** 

- 27th power outage

Inquiries and Complaints: (see Township master list)

Locates: (see Township master list).



Date: May, 2024

Prepared by: Sarah Telford/Ryan MacKay/Jeff Johnston

# **WASTEWATER**

### **Lucknow WW**

Certificate of Approval = 750m3/day

**Exceedances**: flows

Flows:

- April flows: 1469 m<sup>3</sup> max daily flow; 765.77m<sup>3</sup> avg daily flow (102.1% - over capacity).

\*Please note that the system is over capacity for most days December through March\*

Non-Compliances: None

**Equipment Issues:** 

- Check valve for pump #3 at LLS needs replacing

**General information:** 

- Duckweed weir has been installed in cell #3

- RIB repairs have been completed

- Winter storage is no longer being used, back to RIBs

Sewer Main Breaks and Leaks: None reported.

**Power Outages:** 

- 27th Power outage

**Complaints:** (see Township master list) **Total Locates:** (see Township master list)

## **RIPLEY WW**

Certificate of Approval = 600m3/day

Exceedances: None

Flows:

- March flows: 1559m³ max daily flow; 473.67 m³ avg daily flow (78.94% capacity).

Non-Compliances: None Equipment Issues: None General information:

- Spring discharge is complete
- Will be keeping the alum treatment higher to avoid the large dosing prior to discharges
- BMRoss looking at dumping station options to limit chances of spills and danger to operators
- Cell #3 work has been completed by Kemptons:
  - scraped the perimeter and lined with "riprap"
  - scraped down the road and added gravel

Alarms:

Power outage

Sewer Main Breaks and Leaks: None reported

**Power Outages:** 

- 27th power outage

**Complaints**: (see Township master list)



Date: May, 2024

Prepared by: Sarah Telford/Ryan MacKay/Jeff Johnston

**Total Locates**: (see Township master list)

# **Ongoing Issues/Recommendations:**

# WATER:

Valve turning booked to start in April/May time frame.

Flushing has started in the Lakeshore

- Manhole Inspections are scheduled to start soon

Hydrant markers will be changed out with each seasons' flushing (on for winter, off for summer)

# **WASTEWATER**:

**Lucknow**: Nothing new to report. **Ripley**: Nothing new to report.

