## Municipality of Huron-Kinloss Pine River Water Quality Monitoring Program 2022 Sampling Results

GREEN Below Guideline

RED => 100 cfu/100mL

GREY No Data

E. Coli (cfu/100mL)
Sample Date

		Sample Date								
SAMPLE ID	LOCATION	Mar 31	Apr 25	May 24	June 30	July 18	Aug 16	Column6	Column7	Column8
PR1	Pine River-'Bridge on Lake Range Road, south of Lurgan Road	280	78	28	27	18	42			
PR3	South Pine River-Bridge on Hwy. 21 at 6th Conc.	122	52	44	64	112	14			
PR4	Pine River Tributary-Bridge on Hwy. 21 North of 6th Conc.	108	16	148	160	20	4			
PR5	Pine River Tributary-Bridge on Hwy. 21 North of 8th Conc.	540	108	20	87	68	146			
PR6	South Pine River-Bridge on Sideroad 25 North of 6th Conc.	1080	30	2	104	58	38			
PR7 - Upstream	Clark Creek-Culvert on Sideroad 25 South of 4th Conc.	209	1080	42	24	160	360			
PR8	South Pine River-Culvert on the 15th North of 6th Conc.	680	136	140	180	220	6			
PR9	Pine River-Bridge on the 15th South of 10th Conc.	340	48	138	192	4	20			
PR10	Royal Oak Creek-Bridge on the 15th North of the 12th Conc.	2400	94	64	1600	500	200			
PR11	Royal Oak Creek-Cuvlert on Sideroad 5 north Huron-Kincardine East	5600	1700	126	640	Dry	Dry			
PR12	Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 12th Conc.	126	58	190	2100	940	320			
PR13	South Pine River-Bridge on Huron Twp./Kinloss Twp. Boundary South of 8th Conc.	940	34	360	400	460	66			
PR17 - Upstream	Pine River Tributary-Southern Culvert on South Baseline Road North of 4th Conc.	720	148	214	600	2700	1220			
PR18 - Upstream	Pine River Tributary- Middle Culvert on South Baseline Road North of 4th Conc.	62	80	350	120	320	190			
PR19 - Upstream	Clark Creek-Southern Culvert on South Baseline Road North of 2nd Conc.	207	54	* UAL	172	30	56			
PR20	Beach at Hwy. 86 -Amberely Road.	Ice Cover	4	* UAL	15	4	28			
PR21	Beach off of Attawandron Road-Public Walkway	Ice Cover	6	* UAL	51	10	62			
PR22	Beach-Point Clark Swimming Area	Ice Cover	6	* UAL	21	98	20			
PR23	Lurgan Beach-Public Walkway	Ice Cover	20	* UAL	36	8	34			
PR24	Beach at 6th Conc.	Ice Cover	6	* UAL	81	4	22			
PR25	Beach at 8th Conc.	Ice Cover	24	* UAL	106	10	22			
PR26	Beach at 10th Conc.	Ice Cover	20	* UAL	84	2	72			
PR27	Boyd Creek at Hwy. 21 before Amberely	360	14	* UAL	122	36	7			
PR29	Boyd Creek on Sideroad 20 North of 6th Conc.	520	56	* UAL	186	240	70			
PR30	Eighteen Mile Creek at Hwy. 21 before Amberely	91	58	* UAL	37	146	12			
PR32	Eighteen Mile Creek on the 15th North of 2nd Conc.	1360	52	* UAL	27	18	38			
B4	Clark Creek at the Lake	940	68	* UAL	99	10	66			
5	Ditch at field drain outlet, Lake Range Road	19	580	* UAL	260	Dry	Dry			
6	New outlet to Clark Creek across from 3491 2nd Conc.	1000	70	* UAL	110	70	98			
8	Jardine Creek at Abenaki St.	55	20	* UAL	880	640	68			
9	Jardine Creek at Seneca	No Sample	28	* UAL	No Sample	Dry	Dry			
12	Halfway to lake from Road	132	440	* UAL	900	540	300			
13	CSP where creek crosses Huron Rd.	30	14	* UAL	620	Dry	13			
17	Outlet in Jardine Creek between sites 11 & 12	148	50	* UAL	140	106	600			

<sup>\*</sup> UAL - Unreliable Age Limit (Time from sample to analysis exceeded; courier delay), No sample - Unable to obtain sample